


# Aftershock Training

Procedure






The Basics


- Basic Safety
- Specified Training
  - o Ti er System
- Requirements to Pass










Whe	n do you need to wear safety glasses? *
0	When you near the machine
0	Only if you are working on machines
0	Whenever their is any work being done in the lab
0	Never













#### T i e r s 2 + 3









### T i e r s 4 + 5

#### Tier 5

Tier 5 (not yet available)
will be on the robot's
components and is necessary in
order to work in the pit.




Metal Lathe 4: Tier 4



Metal Lathe 3: Tier 4



Metal Lathe 2: Tier 4





g




















Thank you for listening!

Any comments, questions, concerns?

## S o c i a 1 s

Check out our socials below

Website https://www.first263.org

Instagram frc 263

Facebook Sachem Aftershock Team 263

Twitter FRC 263

Emil sachemobotics agmil.com

